

Product Bulletin



RV, BOAT & AIRCRAFT WAX™

Product Description:

Easy to use. Quickly removes dull film, oil smudge, oxidation and light scratches on all painted, gel coat, fiberglass, chrome and aluminum surfaces. Leaves a high gloss, carnauba wax shine that lasts for months.

- RV: Removes oxidation, road grime and black streak marks near joints.
- **BOAT:** Removes fresh and salt water marine build-up and gives new life to gel coats. Protects against prolonged exposure to sun and salt air.
- AIRPLANE: Removes jet fuel build-up and reduces surface tension for maximum air speed, handling and fuel efficiency.
- PLEXIGLAS®: Cleans and removes fine scratches that distort vision and clarity.

Product Details:

VOC Compliant NPE Free Phosphate Free

pH: 8.5 Color: Pink

Fragrance: Floral

Packaging: Quart: P-38-Q





Features & Benefits:

One-Step Cleaner & Wax

Removes light scratches, oxidation, black streaks, marine, & jet fuel buildup, water spots, bird droppings and More

Carnauba Wax and Polymer Resins Offer a Long Lasting High Gloss Shine

For Use on All Painted Surfaces, Gel Coat, Fiberglass, Chrome and Aluminum Surfaces

Application: Shake well before using. Read label before use. See SDS for more information.

Hand Use: Apply product to a clean microfiber wax applicator and spread evenly over small area of painted surface, rubbing well in a circular motion. Let dry to a haze (1 min.) and wipe off with a clean microfiber towel. Polish by hand to a high gloss, turning towel while wiping down.

D/A Polisher: Use a PRO® YU-6 Yellow Polish/Finish Pad. For more aggressive action, use a PRO® BW-6 Black/White Microfiber Polish Pad. Apply product to pad. Set D/A polisher speed to 4-5. Turn on polisher and buff with adequate pressure, spreading product evenly over surface. As product disappears, reduce pressure and polish to a glossy finish. Clean pad often to remove contaminants.

High Speed Buffer: Use a PRO® RV-85-C Charcoal Foam Polish Pad. Apply product to pad and spread evenly over small area of paint surface before buffing. Buff with adequate pressure at 1500-2300 rpm. As product disappears, reduce pressure and polish to a high gloss. Clean pad often to remove contaminants.

Helpful Tips:

Keep from freezing (32 °F/0 °C). Do not apply in direct sunlight or onto a hot surface. Polish one section at a time.

Safety Data Sheet:

GHS Compliant. SDS can be found online at www.prowax.com.



