



PRO® and Burford's® are registered trademarks of BAF Industries.

The Professional's Choice!  
Since 1935

# PRODUCT *Bulletin*



- **Removes Contamination From Organic & Inorganic Fallout**
- **Thick , Ready to Use Formula Clings to the Surface**

- **Mild Oxalic Acid Formula**
- **Quickly & Safely removes Petroleum Deposits, Rail Dust & Mineral Deposits**

## C-45

# POWER LIFT™ Fallout Liquid

### FEATURES AND BENEFITS

C-45 Power Lift™ Fallout Liquid is a mild acid base cleaner that removes organic and inorganic contaminants from automotive paint finishes quickly and easily.

Simply apply the thick liquid to affected area. Wait 3 - 5 minutes and rinse off. It clings to the surface of the paint, lifting and loosening contaminants that are lying on top or imbedded in outer paint layer. It is also an excellent remedy for acid rain removal. C-45 Power Lift™ has the quality of being strong enough to get the toughest fallout to release, yet is gentle enough to protect the surface from further damage.

This product is a fast acting formulation that is far superior in speed than other costly methods of removal. It will not harm glass or chrome and will not soften, fade or discolor finish.

### RECOMMENDED FOR

Great for new car prep. Safe for use on all automotive finishes that have had fallout damage or have been subjected to surface rust, water spotting and acid rain stains.

Use Power Lift™ first before trying more expensive and possibly damaging methods of surface contamination removal.

### APPLICATION

**Shake well before using.** For best results, apply to a cool surface out of direct sunlight. Rinse automobile thoroughly to remove loose surface dirt. Apply C-45 Power Lift™ at full strength to the affected areas. Pour C-45 liberally onto a sponge or wash mitt and apply to damaged vehicle finish, rubbing lightly to help loosen fallout deposits.

Allow the necessary time for the product to work, usually 3-5 minutes is sufficient. Rinse thoroughly with water to flush away contaminants. Wash vehicle with C-60 Super Car Wash Liquid. This will neutralize any fallout remover residue left on the vehicle. Rinse and wipe dry with a chamois.

### SPECIAL NOTES

Keep off aluminum and plastic moldings. Do not apply to a hot surface or let dry on surface. Product is activated while wet. Reaction stops if product dries. Hot weather will make product dry quicker, limiting effectiveness.

### PACKAGING

GALLON/4 PER CASE  
5 GALLON CUBE  
55 GALLON DRUM